

# Improving Reliability of Dunbar D10Y 3.75” WRSV Seals

By Augustine CHILAKA, Stacey THORNTON (TOTALENERGIES UK); Kevin PHILIPS (Oilenco)

# Overview




- Well History & WRSV Challenge
- Analysis of WRSV Service History
- Selection & Qualification of Oilenco REACT Seal Stack
- Results Realized
- Conclusion

# Well History & Challenge



- Well History
  - D10Y is a 28-years producer on Dunbar platform
  - Its 4 ½" STV SideGuard DHSV which failed inflow test in 2015
  - WRSV has been used to operate the well since 2015
  - WRSV performance was hitch free initially & its reliability deteriorated over time
- Requirement/Challenge
  - Reliable and available WRSV for well operation
  - Lost production
- Options to Resolve Challenge
  - Intervention with WRSV
  - Workover → Not favoured by legacy asset economics



# Analysis of WRSV Service History

- WRSV Failure Overview
  - 2015 – 2016: WRSV w/Crimp seals → 3-failures
  - 2016 – 2022: WRSV on Swellable Seals → 6-failures
- Reliability Assessment
  - Total installation count – 16
  - Successful – 6
  - Failures – 10
  - Reliability ~ 10% @ 85% confidence
- Other facts
  - WRSV passes inflow tests after installation
  - Downhole camera did not indicate any clear damage to sealbore
  - Mild scoring on recovered assemblies alludes to potential damage in the Side Guard DHSV cavity

2021



Recovered  
WRSV with  
swellable seals

2022




Recovered  
WRSV with  
swellable seals

# D10 Flowing & Shutin Wellhead Parameters




TotalEnergies




Well Restart Issue after production shut-in

# Deductions & Solutions Proposed



- Preliminary Deductions from WRSV Failures
  - Successful inflow test of flapper → No problem with WRSV flapper
  - Inability to control / operate WRSV via control line → Problem with WRSV body seals/sealbore
  - Some swellable seals having difficulty to retain control line integrity at installation → Seal configuration not fit-for-sealbore condition
  - Most recent swellable seal at installation but not retaining control line integrity after well shut-in → Loss of seal integrity (probably driven by pressure & temperature change)
  
- Possible Solutions
  - Controlled bleed off for control line pressure to minimize fatigue on WRSV seals → not feasible due to instrumentation layout
  - Reduce control line operating pressure → Little room to manoeuvre (350bars Control line pressure vs 180bars SIWHP)
  - More resilient seal stack which is validated to meet with well temperature cycle → Testing of Oilenco REACT seal stack
  - Energized Seal system for WRSV Sealing → Interwell IVC

# Peculiarity of New Concept Oilenco Seals on WRSV






Old System

New System

• Old System


• New System  
- Oilenco REACT seal stack



# Qualification Test Program



Test Fixture



- Install REACT seal stack into test fixture
- Objective 1 - Simulate initial WRSV sealing after WRSV changeout
- Objective 2 - Check gas ingress into control line when well is shut-in
  - Test seals from below with N<sub>2</sub> gas up to 4.8kpsi differential & monitor from Bryco Control line: 3-times → OK. Hold 4.8kpsi x 1hr → OK
- Objective 2 - Simulate well startup/production (hot)
  - Heat up to 100°C in oven & 7.5kpsi control fluid in upper test port overnight
  - Test seals from below with N<sub>2</sub> up to 4.8kpsi differential in 1kpsi increments & monitor from Bryco control line: 3-times
- Objective 3 - Simulate well shut-in & restart → Performed 3x
  - Apply 5kpsi N<sub>2</sub> gas with 200psi Bryco
  - Cool and leave to stand overnight → Simulate closed flapper
  - 5kpsi N<sub>2</sub> bled off and 5000psi Bryco applied above → simulate opening cold well
  - Increase temp to 100°C and stable overnight → simulate production restart
  - Increase Bryco to 7500psi → Simulate hold open flapper
  - Bleed off 7.7kpsi Bryco and apply 5kpsi N<sub>2</sub> below and cool fixture → simulate shut-in



# Installation & Results



- WRSV was installed in June-2023 but there were challenges with the lock
  - Control line integrity held @ 350bars while WRSV was in the well
- WRSV assy recovered and replaced in Nov-2023
  - All the WRSV REACT seals were intact upon recovery
  - Control line integrity confirmed after installation
  - Successful WRSV leak test
  - Well put on production without issues




*Recovered WRSV  
in Nov-2023*

Year	Uptime (dates)	Uptime (days)	Downtime (days)
2021	1-Jan-21 to 17-May-21	75	290
2022	12-Jun-22 to 11-Aug-22	60	264
	14-Oct-22 to 24-Nov-22	41	
2023	24-Nov-23 to 31-Dec-23	37	328
2024	01-Jan-2024 till date	On production	


*Abridged well up time analysis from 2021*

# Conclusions



- 3.75” WRSV was refurbished to accommodate New Oilenco REACT Seal Stack
- Performed rigorous validation testing of Oilenco REACT Seal Stack vis-à-vis D10 Operating Conditions.
- WRSV with Oilenco REACT Seal Stack was installed and recovered with seals intact
- WRSV is currently installed and well on production without WRSV issue(s)
- Investment into a rigorous testing Programme can be more effective than off-the-shelf solutions

# Disclaimer and copyright reservation



## **Definition - TotalEnergies / Company**

The entities in which TotalEnergies SE directly or indirectly holds an interest are separate and independent legal entities. The terms "TotalEnergies", "TotalEnergies company" and "Company" used in this document are used to refer to TotalEnergies SE and its affiliates included in the scope of consolidation. Similarly, the terms "we", "us", "our" may also be used to refer to these entities or their employees. It cannot be inferred from the use of these expressions that TotalEnergies SE or any of its affiliates is involved in the business or management of any other company of the TotalEnergies company.

## **Disclaimer**

This presentation may include forward-looking statement within the meaning of the Private Securities Litigation Reform Act of 1995 with respect to the financial condition, results of operations, business, strategy and plans of TotalEnergies that are subject to risk factors and uncertainties caused by changes in, without limitation, technological development and innovation, supply sources, legal framework, market conditions, political or economic events.

TotalEnergies does not assume any obligation to update publicly any forward-looking statement, whether as a result of new information, future events or otherwise. Further information on factors which could affect the company's financial results is provided in documents filed by TotalEnergies with the French *Autorité des Marchés Financiers* and the US Securities and Exchange Commission.

Accordingly, no reliance may be placed on the accuracy or correctness of any such statements.

## **Copyright**

All rights are reserved and all material in this presentation may not be reproduced without the express written permission of TotalEnergies.