
HIGH RESOLUTION ACOUSTIC IMAGING FOR DOWNHOLE DIAGNOSTICS

Vishal Sharma Director – Sales, Scandinavia





ULTRASOUND 1980

ULTRASOUND 2022



SPECIFICATIONS

DIAMETER 2.88" OD

PRESSURE 15,000 psi

TEMPERATURE 150 °C

DATA CAPTURE 41 Gb/s



STORAGE 2 TB



RESOLUTION 0.01 in / 0.25mm



DELIVERY

MEMORY OR REAL TIME



LOGGING SPEED

9.1 m/min

















APPLICATIONS

Well Integrity







Burst Pressure




Completions Optimization




Sliding Sleeves



Plug Damage



Perforation Analysis




Fiber Clamp Mapping

Intervention



Downhole Valves



Obstructions




Connections






APPLICATIONS


Slotted Liner




Outside Corrosion / Metal Loss




Ovalization / Collapsed pipe



Downhole Safety Valves




APPLICATIONS






3D VIEWER






10X SPE PAPERS




Perforation Erosion Statistics on 30k Perfs



Plug Induced Casing **Damage Statistics**



Complex Perforation Shape Behavior



Advanced Well Integrity

SPE-205933



SPE-209142

Robotics & Acoustic Imaging of Obstructions



Casing Thickness and **Burst Pressure**



Perforation Entry and Exit Hole Analysis



Geometric Quantification of Eroded Perforation



Mapping Permanent Fiber Optic Lines





Refrac For Under-Stimulated Stages





Email: vishal.sharma@darkvisiontech.com



